Under Review Notification

Product #: RB T101983 Raised By: Vanessa Morel

Date: 2019.10.31 Product Name: SLINED SOCKET WRENCH

		"Y" or "N" Required for Each Part									
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RB T101983	RB T101983 Rev	Υ	Υ	Ν	Υ	Υ	Ν	N	N	19-1145	See below

Description of Issue:

Issues stated on ADR (Dimensions issue)

RB T101983 and item -1 must be put on HOLD in Plex

RB T101983 Finish good stock must be put in quarantine

Item -1 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

QC Coordinator

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: **VP Operations** Director of Engineering Customer Support Manager **Technical Support**

> **Director of Operations** Chief Engineer **Production Engineers** Product Manager - Solutions Provider Director Quality Assurance **Engineering Project Managers Production Planners** Supply Chain Director / Senior Buyer **Engineering Clerk Purchasing Manager** Marketing Eugene